

LRQA

LRQA

LRQ/

LRQ/

LRQ/

LITTER

LRQ/

LRQ/

LRQA

LRQ/

LRQ/\

LRQA

LRQ/\

LRQA

LRQ/\

LRQ/

## **Certificate of Approval**

This is to certify that the Management System of:

# EDP Renewables North America LLC

1501 McKinney Street, Houston, TX, 77010, United States

has been approved by LRQA to the following standards:

ISO 14001:2015

Approval number(s): ISO 14001 - 00032875

This certificate is valid only in association with the certificate schedule bearing the same number on which the locations applicable to this approval are listed.

The scope of this approval is applicable to:

Maintenance and Monitoring of Solar Parks and Wind Farms.

Mestatales

#### Marta Escudero

Regional Director, United Kingdom and Americas (UKAM)

Issued by: LRQA Limited





#### **Certificate Schedule**

| Location                                                                                 | Activities                                                                |
|------------------------------------------------------------------------------------------|---------------------------------------------------------------------------|
| Corporate Office 1501 McKinney Street, Houston, TX, 77010, United States                 | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Arbuckle Mountain 9251 Highway 77 South, Davis, OK, 73030, United States                 | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Lost Lakes<br>1481 135th Avenue, Lake Park, IA, 51347,<br>United States                  | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Crossing Trails 0902 County Road 16, Siebert, CO, 80834, United States                   | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Kittitas Valley<br>3701 Hayward Road, Cle Elum, WA, 98922,<br>United States              | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Marble River/Jericho Rise 11 Marble River Way, Churubusco, NY, 12923, United States      | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Top Crop 111 Watters Drive, Dwight, IL, 60420, United States                             | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Rattlesnake Road/Wheat Field 72650 Rattlesnake Road, Arlington, OR, 97812, United States | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Quilt Block<br>340 Donahoe Drive, Darlington, WI, 53530,<br>United States                | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |



LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Issued by: LRQA Limited, 1 Trinity Park, Bickenhill Lane, Birmingham B37 7ES, United Kingdom

Page 2 of 6

**LRQ**/

LRQA

LRQA

**LRQ**A

LRQA



#### **Certificate Schedule**

| Location                                                                                      | Activities                                                                |
|-----------------------------------------------------------------------------------------------|---------------------------------------------------------------------------|
| Meadow Lake<br>6072 South State Road 43, Chalmers, IN, 47929,<br>United States                | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Los Mirasoles<br>41420 FM 490, McCook, TX, 78541, United States                               | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Pioneer Prairie and Prairie Star 134 North Industrial Street, LeRoy, MN, 55951, United States | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Reloj del Sol<br>875 FM 3169, San Ygnacio, TX, 78067,<br>United States                        | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Hog Creek<br>1714 County Road 95 Building G, Ada, OH, 45812,<br>United States                 | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| <b>Timber Road</b><br>9630 State Road 49, Payne, OH, 45880,<br>United States                  | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Lone Valley Solar<br>8500 Camp Rock Road, Lucerne Valley, CA, 93501,<br>United States         | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Cameron Solar<br>5585 Cameron Road, Cameron, SC, 29030,<br>United States                      | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Blue Canyon<br>3109 State Highway 19, Carnegie, OK, 73015,<br>United States                   | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |



LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Issued by: LRQA Limited, 1 Trinity Park, Bickenhill Lane, Birmingham B37 7ES, United Kingdom

Page 3 of 6

LRQA

**LRQ**A

LRQA

. . . . .

LRQ/

I ROA

LRQA

LRQA

LRQ/

LRQA

LRQ/

LRQA

LRQA

LRQA

LRQA

LRQ/\

LRQA

LRQ/

LRQ

LRQ/



### **Certificate Schedule**

| Location                                                                        | Activities                                                                |
|---------------------------------------------------------------------------------|---------------------------------------------------------------------------|
| Waverly 2201 Shetland Road, Waverly, KS, 66871, United States                   | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Harvest Ridge<br>1458 N County Road 2450 E, Newman, IL, 61942,<br>United States | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Estill Solar 136 Park Avenue West, Estill, SC, 29918, United States             | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Hampton Solar<br>2191 Augusta Highway, Hampton, SC, 29924,<br>United States     | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Wildcat Creek<br>7239 FM 1198, Gainesville, TX, 76240,<br>United States         | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Headwaters 1101 Rainbow Drive, Winchester, IN, 47394, United States             | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Twin Groves 13682 N 2900 East Road, Ellsworth, IL, 61737, United States         | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Lone Star<br>299 FM 604, Abilene, TX, 79601, United States                      | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Prairie Queen<br>1699 3400th Street, Moran, KS, 66755,<br>United States         | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |



LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Issued by: LRQA Limited, 1 Trinity Park, Bickenhill Lane, Birmingham B37 7ES, United Kingdom

Page 4 of 6

LRQA

LRQA

LRQA

LRQA

LRQA

LRQ/

LRQA

LPO/

LRQA

LRQ/

LRQA

LRQA

LRQA

LRQA

LRQ/

LPO/

LRQ/

LRQ

LDO



#### **Certificate Schedule**

| Location                                                                              | Activities                                                                |
|---------------------------------------------------------------------------------------|---------------------------------------------------------------------------|
| Bright Stalk 29292 East 2900 North Road, Chenoa, IL, 61726, United States             | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Maple Ridge/Madison<br>6972 Eagle Factory Road, Lowville, NY, 13367,<br>United States | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Elkhorn Valley 53777 State Highway 237, Union, OR, 97883, United States               | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Rising Tree<br>15600 67th Street West, Mojave, CA, 93501,<br>United States            | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Meridian Way<br>1409 Iron Road, Concordia, KS, 66901,<br>United States                | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Redbed Plains 1421 County Road 1190, Tuttle, OK, 73089, United States                 | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Arkwright Summit 10001 Route 60, Fredonia, NY, 14063, United States                   | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Railsplitter 201 NW Main Street, Hopedale, IL, 61747, United States                   | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Turtle Creek<br>810 Enterprise Drive, Stacyville, IA, 50476,<br>United States         | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |



LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Issued by: LRQA Limited, 1 Trinity Park, Bickenhill Lane, Birmingham B37 7ES, United Kingdom

Page 5 of 6

LRQA

**LRQ**A

LRQA

LPOA

LRQ/

LRQ/\

LRQ/

LRQA

LRQ/

LRQ/

LRQ/

LRQ/

LRQ/

LRQA

LRQA

LRQ/\

LRQ/

LKQ/

LRQ/

LRQ/

LPO/



#### **Certificate Schedule**

| Location                                                                                                                          | Activities                                                                |
|-----------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------|
| Eolica de Coahuila<br>Carretera Federal 40 km 66.074 , General Cepeda, CP25935<br>Coahuila, Mexico                                | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Parque Solar Los Cuervos Carretera 69, Colonia Los Cuervos, Rancho San Bartolo localidad Camposanto, 20395 Aguascalientes, Mexico | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Los Cañones Carretera Federal 40 Saltillo a Torreon Km 66.074., 25935 General Cepeda, Mexico                                      | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| Nation Rise<br>14744 County Road 13, Crysler, KOA1RO, Ontario,<br>Canada                                                          | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |
| South Branch 4344 County Road 16, Brinston, L0E1C0, Ontario, Canada                                                               | ISO 14001:2015  Maintenance and Monitoring of Solar Parks and Wind Farms. |



LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Issued by: LRQA Limited, 1 Trinity Park, Bickenhill Lane, Birmingham B37 7ES, United Kingdom

Page 6 of 6

**LRQ**/

**LRQ**A

LRQA

LRQA

**LRQ**A

LRQA